



## KENDRION Stock List

Part No : 77 500-19B15600

Part No : 86 61106t01

Part No : (OAC009.501521) (stock code OAC0090291)

Part No : ,,,,

Part No : 10 320-05D00/GT050B001.00 (GTB050.000001) (stock code 1031105)

Part No : 100028/0701

Part No : 1125327

Part No : 1129447

Part No : 1143643

Part No : 1145854

Part No : 1145854 Zeichnungsnummer: DBMX8060.11.U123-23

Part No : 1147858

Part No : 1172200

Part No : 1192942

Part No : 13.310.05.203-24V

Part No : 14.512.04.12

Part No : 17320B23 OBSOLETE

Part No : 20030001

Part No : 21 554-08B1

Part No : 21080008

Part No : 21080008, OLV554001A00\_21 55408B1

Part No : 2155408B1

Part No : 2201926

Part No : 307398

Part No : 32 073-02B01

Part No : 32 073-22A00.14

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: [info@adamsint.net](mailto:info@adamsint.net) Web: <http://www.adamsllc.net/>

Get quote now ! [info@adamsint.net](mailto:info@adamsint.net)

Part No : 32 073-22B40  
Part No : 32 073-32B40  
Part No : 32 073-32B40 500V + 10%  
Part No : 32 07302B11 does NOT exist!!!  
Part No : 32 07322A40 - obsolete replaced by 32 07322B40  
Part No : 32 07322B40  
Part No : 32 07332B40  
Part No : 32 07332B43UL  
Part No : 32 07333B40  
Part No : 32 07333■'40  
Part No : 32 173-50E00 (stock code 3211003)  
Part No : 32 173-50E20 3211007  
Part No : 32 173-50E28  
Part No : 32 17350E20  
Part No : 32 17350E28  
Part No : 32 672-04B00  
Part No : 32 672-04B00 (stock code 3261022)  
Part No : 32 67204B01  
Part No : 32- 173-50E28  
Part No : 3207302A01 replaced by 32 073-02B01  
Part No : 3207332B40  
Part No : 3217350E28  
Part No : 33 403-01C00  
Part No : 33 43312A03  
Part No : 3AX1101-2E  
Part No : 3AX1103-34  
Part No : 3WL911-0AD06-0AA0  
Part No : 3WL9111-0AD05-0AA0  
Part No : 40 006-28AE24V01  
Part No : 40 00628AE31V01  
Part No : 4000628AE24V01  
Part No : 40250015  
Part No : 40E 006-28A51.V0124V D.C  
Part No : 40E 006-28A51.V0124V D.C, 100% E.D  
Part No : 40E001 46 A00V02

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States  
Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: info@adamsint.net Web:  
<http://www.adamsllc.net/>

Get quote now ! info@adamsint.net

Part No : 40E00628C02V01 oem Solar Nederland B.V.  
Part No : 41 01E-06K00  
Part No : 41 01E-06K00 24V D.C + EM-EX-24V D.C  
Part No : 41 42607K00  
Part No : 41 476-06A00  
Part No : 41-03E-10K00  
Part No : 41-42609K02  
Part No : 410 6003 4147606A00  
Part No : 4103405K3  
Part No : 41060003  
Part No : 41060033  
Part No : 41090040  
Part No : 41100048  
Part No : 412 11176 033 SO oem  
Part No : 43 111-04E00  
Part No : 43 111/116-04/LCL040050  
Part No : 43 11606D50  
Part No : 430001  
Part No : 4311105 D 00  
Part No : 4311606D50  
Part No : 44030031  
Part No : 44030045  
Part No : 44030066  
Part No : 5004122  
Part No : 50E00118C06W  
Part No : 54.024  
Part No : 56.10.2A  
Part No : 6 CB 200  
Part No : 71 10124C1 900-0099  
Part No : 73 24513E00-0002  
Part No : 73-241-13A00-200  
Part No : 73431-16H07  
Part No : 76 16 E24B00-0006  
Part No : 76 16E-24B00 0007  
Part No : 76 16E24B00-006

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: [info@adamsint.net](mailto:info@adamsint.net) Web: <http://www.adamsllc.net/>

Get quote now ! [info@adamsint.net](mailto:info@adamsint.net)

Part No : 76 431-11H10 0001  
Part No : 76 43110 H03  
Part No : 76 43111h03  
Part No : 7616E24B00-0005  
Part No : 77 10025A00850 - obsolete, replaced by - 77 10025B00850  
Part No : 77 10025B00850  
Part No : 77 500-19B15 0001  
Part No : 77 500-19B15 600  
Part No : 77 50019A15  
Part No : 77 50019B15  
Part No : 77 50019B15-0006  
Part No : 77 50019B15600  
Part No : 77 50024A15  
Part No : 77 60019A00-0001  
Part No : 77 60019A00-0006  
Part No : 81002-09B6  
Part No : 86 12111E00-0001  
Part No : 86 61106T01-0001  
Part No : 86 61111E00  
Part No : 86 61114P01  
Part No : 86 61116E00-0001 obsolete, replacement 86 61116H00-0017  
Part No : 86 61116H00-0017  
Part No : 86 621-04E00  
Part No : 86121-11E00 upgrated to 86 12111E00-0001  
Part No : 86611-06E00  
Part No : 8661107P01-0001  
Part No : 8661109P01-0001  
Part No : 8661116H05 24VDC  
Part No : 866111P011  
Part No : 902.00600  
Part No : 99300000000000  
Part No : BAC29PM54  
Part No : BFK552-18  
Part No : BMX 3030.11.00.A-16  
Part No : BMX3030.11.00.B11

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: [info@adamsint.net](mailto:info@adamsint.net) Web: <http://www.adamsllc.net/>

Get quote now ! [info@adamsint.net](mailto:info@adamsint.net)

Part No : Brake VAR 0006 (stock code 73411HV006)  
Part No : CDR 030  
Part No : CH-8915 TYPE:GSU 50 ZII 041  
Part No : CLHP0350051  
Part No : EMV5058.01.B2102  
Part No : FD:016 TYPE:GH72E/52  
Part No : GHBX4055.01.B2122-03  
Part No : GHBX4055.01.B2122-03 (1185447)  
Part No : GHE062.501501  
Part No : GHX5577.22.00-01 (OEM for ALÃ– Deutschland)  
Part No : GL40E/86  
Part No : GLA090.503001  
Part No : GLE040.009001  
Part No : GLE040.506501  
Part No : GSS 50 ZI U:24V  
Part No : GSU 50 ZI/5189 U:24V  
Part No : GSU 50.Z.I 285  
Part No : GSU50ZI/5189  
Part No : GSU50ZII041  
Part No : GT 0145 A 001  
Part No : GT015B001  
Part No : GT018B001 Obsolete, replaced by GTB018.000001  
Part No : GT032B001.00  
Part No : GT050B001.00  
Part No : GT050B001.10  
Part No : GT050R 153.01  
Part No : GT25 R 002.00  
Part No : GT50R04  
Part No : GT50R06201  
Part No : GT50R62  
Part No : GT63R001.01  
Part No : GT70 R 002.11  
Part No : GTB018.000001  
Part No : GTB025.000001  
Part No : GTB040.000001

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: [info@adamsint.net](mailto:info@adamsint.net) Web: <http://www.adamsllc.net/>

Get quote now ! [info@adamsint.net](mailto:info@adamsint.net)

Part No : GTB063.000001  
Part No : GTB063.100001  
Part No : GTB150.000001  
Part No : GTH025.100001 (stock code GT025H060)  
Part No : GTR025.025501  
Part No : GTR048000A07  
Part No : GTR063.000001  
Part No : GUA060.507501  
Part No : HAGT339816P0022  
Part No : HAGT339816P0023  
Part No : HAGT339816P0031  
Part No : HAGT339816P0032  
Part No : HBMX5050.01.A00-42  
Part No : HSLX6040.11.00-02  
Part No : I-GT 50 R 001  
Part No : I-LLV040001  
Part No : I-LLV040002  
Part No : KENDRION - 4105414G03  
Part No : KENDRION - 50003635  
Part No : KENDRION - 76 43111h03  
Part No : KENDRION - BFK458-12E / 00419593  
Part No : KENDRION - GTB025.00001  
Part No : KENDRION - GTX025.000001.2  
Part No : KENDRION - HSLX 6040.11.00-02  
Part No : KENDRION -01 32003800  
Part No : KENDRION -01 32005800  
Part No : KHP800 oem for siemens  
Part No : KLEINMAGNET GB4A2/3.220/896 OHM/54W  
Part No : KLM022.240001  
Part No : KLMS22Z  
Part No : KLMSB 22  
Part No : KLMSB 40 Z/4085  
Part No : KLMSB22FA/3734C  
Part No : KLMSB22z-5585  
Part No : KLMSB24FA/3734A

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: [info@adamsint.net](mailto:info@adamsint.net) Web: <http://www.adamsllc.net/>

Get quote now ! [info@adamsint.net](mailto:info@adamsint.net)

Part No : KLMSB30Z024  
Part No : KLMSB40Z  
Part No : KLMSB40Z/4085  
Part No : KLMU 22 FA  
Part No : KLMU22FA/6032  
Part No : KLMU22Z248  
Part No : KLMU30FA011  
Part No : KLMU30FA359  
Part No : KLMU30Fa011 (stock code KLMU30011)  
Part No : KLMU30Fa359 (stock code KLMU30013)  
Part No : KLMZ22Fa001  
Part No : KQB328 BS  
Part No : KQY866C2  
Part No : KRU939  
Part No : KRW533  
Part No : LCL040050A13 (LCL0400022)  
Part No : LCL0500003  
Part No : LCL0500004  
Part No : LHP02504A00  
Part No : LHP0350034  
Part No : LHP0350140A62  
Part No : LHP035053A-10  
Part No : LHP035053A-15  
Part No : LHP035053A00  
Part No : LHR060000A10  
Part No : LHR0700002 OBSOLETE- REPLACED BY  
LHR070000A00\_GHU7142.01.103 24V D.C (Stock Code : GHU71421)  
Part No : LHR070000A00\_GHU7142.01.103 24V D.C (Stock Code : GHU71421)  
Part No : LLV040001 AND LLV040002  
Part No : Locking Solenoid Plug Connector RSG6  
Part No : MAGNET TYP KLMSB 22 FA/3734  
Part No : NR.43006  
Part No : OAC003.564020.  
Part No : OAC005 .500043  
Part No : OAC006.500060  
Part No : OAC007061

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States  
Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: info@adamsint.net Web:  
<http://www.adamsllc.net/>

Get quote now ! info@adamsint.net

Part No : OAC007071  
Part No : OAC009.255500  
Part No : OAC009.500081  
Part No : OAC009.500132  
Part No : OAC009.500194  
Part No : OAC009.500388  
Part No : OAC009.502132  
Part No : OAC009.521200  
Part No : OAC009.525600 OAC009081  
Part No : OAC009002  
Part No : OAC009026  
Part No : OAC009046  
Part No : OAC009056  
Part No : OAC0090562  
Part No : OAC009059  
Part No : OAC009086  
Part No : OLV554001A00\_21 55408B1  
Part No : OMW516002A00  
Part No : OMW516002A00 (2 pcs.)  
Part No : OSR127 500031  
Part No : OSR127031  
Part No : OSR501002  
Part No : Obsolete 32 67204B01 replaced by 32 67204B00  
Part No : RSG6  
Part No : SMX5040.11.00  
Part No : SO75482  
Part No : TEILE-NR. 21080008  
Part No : TVM50RIIG230V  
Part No : TVM50RIIâ€  
Part No : TYP 41 903-09A00  
Part No : TYP GSS 50 ZI  
Part No : TYP KLMU30FA359,  
Part No : TYP LLV050058  
Part No : TYPE 10 9004A00 NR.KDV562 S3 24V 100% ED 0,21A  
Part No : TYPE 10 9004A00 NR.KFF753 T5 24V 100% ED 0,21A

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: [info@adamsint.net](mailto:info@adamsint.net) Web: <http://www.adamsllc.net/>

Get quote now ! [info@adamsint.net](mailto:info@adamsint.net)

Part No : V45 -N - - 24VDC

Part No : V45 N

Part No : V45-N-24VDC

Part No : WS 7/28

Part No : WSB003.564200 replaced by OAC003.564020

Part No : WSB003566200WS3B/38

Part No : WSB009.008001

Part No : WTI003.501001

Part No : Z0510MSD.40R050111.M3

Part No : o1020001

Part No : repair kit for brake 77 100-25■■■00